Connecting a DataMan Through Ethernet

1. Connect the slide-in module to your DataMan.



2. With a 2.5 mm Allen wrench, tighten the screws so that the slide-in is firmly locked.



3. Insert the plug and slide the cable lock up to the reader and twist the cable lock in place.

